


Manway Cover Detail



| | |
|--------------|-----------|
| Outside Dia | |
| No of bolts: | |
| Bolt length: | |
| Bolt dia.: | |
| Nom. size: | 18" |
| Rating: | 300# |
| Type: | WELD NECK |

Code Plate

U-1 on hand Y/N Y
 Heat Treat Y/N N
 X-Ray Y/N N

Tank Openings

Tank Details

Description

Dimensions

| | | |
|--------------------------|-----|-----------|
| O/A Length | A - | 99' 6" |
| Length - weld to weld | B - | 87' 9.71" |
| Diameter of Tank | C - | 11' 9.5" |
| Weld to End | D - | 10.6" |
| Width of Piers | E - | 18" |
| C/C of Piers | F - | |
| C/L of Piers to Weld end | G - | 12' |
| Ht. Of tank above grade | H - | |
| | K - | 10' |

No Size Type

Description

| | | | | | | | |
|----|-----|--|--|-----------------------|--------------|-----------------------|---------------------------|
| 1 | 1" | | | Manufacturer: | RILEY BEAIRD | Type of Head | |
| 2 | 1" | | | Date of manufacture | 8/19/1975 | Tank Capacity | USWG 77,778 |
| 3 | 4" | | | Working Pressure | 275 PSI | Tank Weight | estimated 176,926 |
| 4 | 6" | | | National Board Number | 37605 | Tank Shell | THICKNESS 1 3/16" |
| 5 | 2" | | | Serial Number | 117738-01-1 | Tank Head | THICKNESS .72" |
| 6 | 3" | | | Steel Type: | SA 615-70 | Pier Type | concrete / saddles / flat |
| 7 | 4" | | | Jurisdiction # | | Tank Saddles | yes |
| 8 | 18" | | | Pressure Gauge | | Wear Pads | |
| 9 | 3" | | | Liquid Level Gauge | | | |
| 10 | | | | Thermometer | | | |
| 11 | | | | Paint Condition: | GOOD | | |
| 12 | | | | Color: | WHITE | | |
| 13 | | | | Relief Valve Type | | Information taken by: | CHERRY DEMOLITION |
| 14 | | | | Test Date | | Date: | |
| 15 | | | | | | Tank Location | LA PORTE, TEXAS |