


Manway Cover Detail



| | |
|------------------------|-----------|
| Outside Dia | 25" |
| No of bolts: | 16 |
| Bolt length: | 7" |
| Bolt dia.: | 1-1/8" |
| Nom. size: | 18" |
| Rating: | 150# |
| Type: | Long Neck |
| Height of above shell: | 14" |

U-1 on hand Y
 Heat Treat N
 X-Ray N

Tank Openings

Tank Details

Description

Dimensions

| | | |
|--------------------------|-----|------------|
| O/A Length | A - | 67' 1" |
| Length - weld to weld | B - | 62' 3" |
| | C - | 108" |
| Weld to End | D - | 2' 4" |
| Width of Piers | E - | 15" |
| C/C of Piers | F - | 36' |
| C/L of Piers to Weld end | G - | 13' 1-1/2" |
| | H - | 13' 1" |

| No | Size | Type | Description | Tank Details | | |
|----|--------|------|-----------------------|-----------------------|-----------------|---------------------------------------|
| 1 | 2" | 300# | Liquid Bottom Opening | Manufacturer: | Bethlehem Steel | Type of Head |
| 2 | .75" | NPT | Thermo Well | Date of manufacture | 1948 | |
| 3 | 2-1/2" | NPT | Float Gauge | U Stamp | U 69 | Tank Capacity |
| 4 | 1/2" | NPT | Pressure Gauge | Working Pressure | 200 | USWG |
| 5 | | | | National Board Number | 708 | Tank Weight |
| 6 | | | | Serial Number | HA 11293 | estimated |
| 7 | 18" | 150# | Manway | Steel Type: | | Tank Shell |
| 8 | | | Manway Openings | Mfg # | | Tank Head |
| 9 | 3" | 300# | Pressure Relief Valve | Jurisdiction # | | |
| 10 | 3" | 300# | Spare | Pressure Gauge | y | Pier Type (Concrete / saddles / Flat) |
| 11 | 1" | NPT | Threaded Opening | Liquid Level Gauge | y | Tank Saddles |
| 12 | 1" | NPT | Threaded Opening | | | Concrete |
| 13 | 1-1/2" | NPT | Threaded Opening | Paint Condition: | good | no |
| 14 | 1-1/2" | NPT | Threaded Opening | Color: | white | |
| 15 | 2" | NPT | Threaded Opening | | | Information taken by: |
| 16 | | | | Relief Valve Type | multi port | Gary M |
| 17 | | | | Test Date | na | Date: |
| | | | | | | 5 5 2009 |
| | | | | | | Tank Location |
| | | | | | | GM Janesville WI |